Group 5 Front Suspension

GENERAL:

This group contains information on the front wheel

suspension components designed to suspend the coach

above the ground.

SPECIFICS: As applicable

...Coil Springs

... Control Arms and Sockets

...Leaf Spring and Attaching Hardware

...Radius Rods

... Shock Absorbers

...Wheel Spindles and Associated Parts

GROUP 5

FRONT SUSPENSION

TABLE OF CONTENTS

PARA	GRAPH	PAGE
5-1	DESCRIPTION	5-3
	a. General b. Front Suspension Components	5-3 5-3
5-2	TROUBLESHOOTING	5-3
5-3	REMOVAL/INSTALLATION	5 -4
	a. General b. Spindle Removal c. Spindle Installation d. Upper Suspension Arm Removal e. Upper Suspension Arm Installation f. Lower Suspension Arm Removal g. Lower Suspension Arm Installation h. Leaf Spring Removal i. Leaf Spring Installation j. Front Shock Absorber Removal k. Front Shock Absorber Installation	5-4 5-45 5-5 5-5 5-777 7-77
5-4	DISASSEMBLY	5-7
	a. Generalb. Leaf Suring Disassembly	5-7 5-7
จิ÷จิ	INSPECTION/CLEANING	5-8
	a. Inspection of Components b. Cleaning	5-8 5-8
5-6	REPAIR	5-8
	a. General b. Upper Suspension Arm Socket Replacement c. Lower Suspension Arm Socket Replacement d. Leaf Spring Replacement	5-8 5-8 5-8
5-7	ASSEMBLY	5-8
	a. Generalb. Leaf Spring Assembly	5-8 5-8
5-8	GENERAL INFORMATION	5-9
	a. Leaf Spring Specifications b. Lubrication of Leaf Spring	5-9 5 - 9




Figure 5-1. Front Suspension System

5-2

GROUP 5

FRONT SUSPENSION

5-1. DESCRIPTION

a. General (fig. 5-1). The coach has an independent front suspension system designed to provide a soft ride over varying road conditions and to prohibit transmittal of road shock from one wheel to another should one wheel pass over an obstruction. A 10-leaf transverse spring, shock absorbers, upper and lower suspension arms and spindle assemblies make up the front suspension system. The 3-inch wide 10-leaf spring, (approximately 5 feet 4 inches long) in bolted to a welded saddle bracket. The spring absorbs road shocks at a rate that varies with the intensity of the disturbance. The higher the deflection the greater the number of leaves that come into play and prevent bottoming of the frame on the bumper pads.

The spring and shock absorbers are attached to the lower suspension arm. The spring is attached by means of shackles. These are connected to the lower (main) leaf at the shackle eye, which is a loop bent in the end of the leaf. A shackle pin passes through the loop and is held in place by a nut on each end. The pin seats in a bushing (bonded center joint), comprised of an elastomer cushion

material bonded to tubular steel, which serves two purposes: it permits the shackle to swing, and it keeps road noise and vibration from being passed from the spring to the frame of the coach.

The front suspension system and components are covered in this Group. For service information on equipment interconnected with the front suspension system, such as steering linkages (Group 7), wheels (Group 8) or brakes (Group 9), refer to the appropriate group. For information on procuring replacement parts, refer to the 2900R Parts Catalog.

b. Front Suspension Components. The suspension system major components consist of a 10-leaf spring assembly, two spindles, two lower and two upper suspension arms, and two shock absorbers.

5-2. TROUBLESHOOTING

Instructions for troubleshooting the front suspension system are contained in table 5-1. When corrective remedies are referenced, they should be accomplished in accordance with the step-by-step procedures.

Table 5-1. Troubleshooting Front Suspension

Malfunction (symptoms) .	Probable causes	Corrective action (remedies)
Spring noise (squeaking)	Lack of lubrication	Lubricate with Valvoline "TECTYL 400-C"; refer to paragraph 5-8b
	Loose U-bolts	Tighten nuts; refer to paragraph 5-31 step (3)
	Loose or worn bushing (bond- ed joints) in shackle	Replace
Spring sag	Overloading or severe opera- tion	Check forward areas for over- loading; move heavy objects toward rear
	Defective shock absorbers	Replace; refer to paragraph 5-31 and k
	Broken spring leaf	Replace; refer to paragraph 5-60

Table 5-1. Troubleshooting Front Suspension (Continued)

Probable causes	Corrective action (remedies)
Defective shock absorbers	Replace; refer to paragraph 5-3j and k
Operation over excessively rough terrain or normal fatigue	Replace; refer to paragraph 5-3h and i
Camber out of adjustment	Adjust alignment cams on uppe suspension arm; refer to Group 7
	Defective shock absorbers Operation over excessively rough terrain or normal fatigue

5-3. REMOVAL/INSTALLATION

a. General. Access to various components of the front suspension system may require the removal of components covered in other groups. For removal or installation instructions for such components, refer to the appropriate group.


b. Spindle Removal.

- (1) Set parking brake and insert chocks under rear tires.
- (2) Jack up front end and install truck stands under front jack points; see figure 5-2.
- (3) To gain access to the spindle, remove wheel, hub and drum; refer to Group 8.

NOTE

If the brake assembly is to be removed and installed on a new spindle, refer to Group 9 for the replacement procedure.

- (4) Place jack under spring eye (center area between shackle halves) and raise enough to relieve (neutralize) tension.
- (5) Remove cotter pin and nut attaching the steering control arm to the spindle and detach control arm (with woodruff key) from spindle.
- (6) Disconnect flexible hose connecting brake line from frame to lower wheel cylinder fitting. Use container to catch fluid; refer to Group 9.



SD-24

Figure 5-2. Jacking Points

(7) Remove four muss from upper end of the four bolts attaching the socket to the lower suspension arm; raise arm as necessary until bolts clear the mount holes.

NOTE

An alternate method for disconnecting suspension arms from the spindle (steps 7 and 8) is to remove the cotter pin and mut from tapered stud of socket and separate it from the tapered mount holes in spindle as follows:

- If socket is to be reused, use a special tool (ball-joint press) to extract socket. If necessary, coax the extraction tool with a few gentle taps with a 40-pound hammer.
- If socket assembly is to be replaced use a "pickle fork" or "tuning fork" and hammer to drive fork prongs between socket head and outer area around spindle mount holes.
- (8) Support spindle assembly and remove four nuts and bolts attaching the socket to the upper suspension arm; remove spindle assembly.
- (9) If replacement of sockets in spindle is necessary, refer to paragraph 5-6 for repair procedures.

c. Spindle Installation.

- (1) Position spindle with sockets installed in lower and upper spindle attaching points and secure with nuts and cotter pins to align with mount holes in lower and upper suspension arms.
- (2) With leaf spring tension removed by jacking (steps 5-3 b (4), attach socket in lower suspension arm mount holes with four 1-3/4 inch bolts with nuts on top end; torque to 36 to 38 foot pounds.
- (3) Attach socket in upper suspension arm mount holes with four 1-1/4 inch bolts with washers and nuts on top end; torque to 46 to 50 foot pounds.
- (4) Install steering control arm (with woodruff key) into hole in the end of lower portion of spindle; secure with nut and cotter pin.
- (5) Connect flexible hose brake line between lower wheel cylinder fitting and tube on frame, and bleed brake system; refer to Group 9.

- (6) Install wheel, hub and drum; refer to Group 8.
 - (7) Remove jacks and wheel chocks.

d. Upper Suspension Arm Removal.

- (1) Repeat jacking procedure in paragraph b steps (1) and (2), then remove wheel to gain access to the suspension arm; refer to Group 8.
- (2) Remove shock absorber; refer to paragraph 5-3 j.
- (3) Remove four nuts and bolts attaching spindle socket to upper suspension arm.
- (4) Remove cotter pin, nut and washers from each end of upper suspension arm pivot spindle (shaft).

NOTE

Place a mark across the cuter end of the alignment cams (both front and rear cams) and on the lower half of the frame mounted block for use in establishing proper positioning of the cam (eccentric alignment hole) during reinstallation.

(5) Remove four bolts, washers and upper arm alignment cam lock that secures bushing splitblock mount to frame block half; remove upper split-block, then remove suspension arm assembly.

e. Upper Suspension Arm Installation.

(1) With thrust washer and alignment cam positioned on each end of suspension arm spindle (shaft), install spindle ends into the frame-mounted halves of the blocks. Align the marks on the cam and the lower half of the frame mounted block, then install upper half of block and secure with cam lock, washer and bolt.

NOTE

Be sure to line up the marks on the cam and block, as improper reinstallation of the alignment cam could change the camber adjustments. If a new alignment cam assembly or a re-bushed cam is installed, refer to Group 7, and establish proper positioning of alignment cam. Torque the hold-down bolts to 32 to 34 foot pounds following positioning of the alignment cams.

- (2) Install washers and nuts on suspension arm pivot shaft (spindle) ends; see preceeding NOTE, then torque nut to 171 to 189 foot pounds; install cotter pins..
- (3) Connect spindle socket to suspension arm mount holes with nuts on top end; torque to 36 to 38 foot pounds.
- (4) Install shock absorber; refer to paragraph 5-3 h.
- (5) Install wheel; refer to Group 8, then remove jacks and wheel chocks.

f. Lower Suspension Arm Removal.

(1) Jack coach as outlined in the procedures in paragraph 5-3 b, steps (1) and (2), then remove wheel to gain access to the suspension arm; refer to Group 8.

- (2) Remove shock absorber; refer to paragraph 5-3 j.
- (4) Remove four nuts and bolts attaching spindle socket to the lower suspension arm.
- (5) Remove two mits and bolts attaching radius rod to lower suspension 21m; detach rod.
- (6) Remove cotter pin and nut from pivot bolt attaching lower suspension arm to frame bracket; remove bolt then remove lower suspension arm.

g. Lower Suspension Arm Installation (fig. 5-3).

(1) With pivot bushing (bonded center joint) inserted in pivot hole on end of the suspension arm, install in frame mount bracket and attach with pivot bolt (head-end forward) and nut; torque nut to 90 to 100 foot pounds, then install cotter pin.




Figure 5-3. Lower Suspension Arm Replacement

- (2) Attach the socket head on the spindle to the mount point on the lower suspension arms with four bolts and nuts (with nuts on upper end); torque nuts to 45 to 50 foot pounds.
- (3) With bushing in place, connect upper ends of spring shackle to lower suspension arm; torque nuts to 171 to 189 foot pounds.
- (4) Install shock absorber; refer to paragraph 5-3 k.
- (5) Attach radius rod end to the two lower suspension arm mount holes using a 1-3/4 inch bolt in the forward hole and a 2-1/4 inch bolt in the rear hole; install and torque lock nuts to 88 to 94 foot pounds.
- (6) Install wheel; refer to Group 8, then remove jack stands and wheel chocks.

h. Leaf Spring Removal.

- (1) Jack coach front end and position support stands as outlined in the procedures in paragraph 5-3 b steps (1) and (2).
- (2) Remove tension from spring ends with jack, remove shackle pins and detach shackles from spring eyes on each end.
- (3) Position a jack under the support plate under center area of spring; support weight of spring and remove four nuts from threads of the U-bolts.
- (4) Lower spring assembly to clear U-bolts, and roll out jack and spring toward front end of coach.

NOTE

The spring center bolt upper round head inserts into a hole in the frame mounted saddle bracket. Early model coaches utilized a bushing to provide a snug fit at this point, but later coaches incorporate a redesigned saddle bracket with a smaller hole i.d. requiring no bushing. If coach has the bushing, retain and reuse when installing a replacement spring.

i. Leaf Spring Installation.

(1) With spring assembly supported on floor jack, roll in from front of coach and position (center) spring under U-bolts.

- (2) Raise spring assembly to insert round head of center bolt into hole in saddle bracket mount hole (be sure bushing is in place on early model coaches per paragraph <u>h</u> (4) NOTE).
- (3) Install four muts on U-bolt threads; torque nuts to 171 to 189 foot pounds, then remove jack supporting spring center.
- (4) Using jack, position spring end eyes to align with holes in lower end of shackles; insert shackle pins and torque nuts to 171 to 189 foot pounds, then install cotter pins.
- (5) Remove jack and jack stands and the chocks from rear wheels.

j. Front Shock Absorber Removal.

- (1) Jack coach front end and position jack stand; refer to procedure in paragraph 5-3 b steps (1) and (2).
- (2) Using jack under leaf spring eye, raise to relieve tension on shock absorber attachment bolts.
- (3) Remove upper and lower shock absorber attachment nuts and bolts, then remove shock absorber.
- k. Front Shock Absorber Installation. Installation of a front shock absorber is accomplished in the same manner as the procedures specified in previous paragraph, except shock absorber is positioned to align with upper and lower mount holes and both attachment nuts/bolts must be inserted and torqued to 212 to 234 foot pounds; remove jacks and wheel chocks upon completion.

5-4. DISASSEMBLY

- a. General. With the exception of the 10-leaf spring, disassembly of the suspension system following removal from the coach consists of separation of two or three components. Refer to the repair section for instructions regarding these assemblies.
- b. Leaf Spring Disassembly. Disassembly of the leaf spring after it is removed from the coach is accomplished as follows:
- (1) Install a C-clamp adjacent to spring center bolt and tighten.
- (2) Remove nuts, bolts and spacer tube from spring clips.

(3) Remove center bolt nut; loosen C-clamp and separate spring leaves.

NOTE

Clips remain attached to the number 5 leaf tip mount hole with rivet.

5-5. INSPECTION/CLEANING

a. Inspection of Components. Inspect components of the front suspension system as outlined in table 5-2.

with the arm removed, by removing the four nuts and bolts attaching socket head to the arm and removing socket. Install replacement socket head on the arm with four 1-1/4 inch bolts with nuts on upper side of arm; torque nuts to 46 to 50 foot pounds.

c. Lower Suspension Arm Socket Replacement. The socket assembly in the lower suspension is replaced in the same manner as the upper suspension arm socket described above, except four 1-3/4 inch bolts are used and the nuts torqued to 34 to 38 foot pounds.

Table 5-2. Inspection of Components

		
INSPECT FOR	METHOD	CORRECTIVE ACTION
Looseness	Check with wrench	Tighten per paragraph 5-31 step (5)
Loose attachment bolts or damage	Visual	Tighten or replace
Looseness	Visual or wrench	Tighten per paragraph 5-3e step (3) and 5-3g step (2)
Breakage	Clean per follow- ing paragraph and visually inspect front and aft edges for cracks	Replace broken leaf per paragraph 5-6d
	Looseness Loose attachment bolts or damage Looseness	Looseness Check with wrench Loose attachment bolts or damage Looseness Visual or wrench Breakage Clean per following paragraph and visually inspect front and aft edges

b. Cleaning. Clean spring leaf outer and upper surfaces with stiff bristle (wire) brush or other suitable method. Standard commercial cleaners can be used, as specified on container, for cleaning and washing of the remaining suspension system components.

5-6. REPAIR

- a. General. Repairs on the front suspension system assemblies consist of replacing components subjected to wear during normal operations.
- b. Upper Suspension Arm Socket Replacement. The socket assembly in the upper suspension is replaced after the spindle has been detached, or

d. Spring Assembly Leaf Replacement. Individual leaves may be replaced by disassembling spring as described in paragraph 5-4 b, inserting new leaf, then reassembling in accordance with paragraph 5-6 b.

5-7. ASSEMBLY

- a. General. The repair section contains assembly instruction for all the front suspension system assemblies other than the leaf spring.
- b. Leaf Spring Assembly (fig. 5-1). To assemble a leaf spring proceed as follows:

- (1) Arrange the leaves as shown, then clamp together with a C-clamp positioned near the center bolt hole.
- (2) Install center bolt with round head on top and use a new 1/2 x 13 nut; tighten nut, then peen center bolt end to secure nut.
- (3) Install clips and secure with bolts, spacer tubes and new $3/8 \times 16$ nuts; peen end of bolts to secure nuts.
- (4) Refer to paragraph 5-3 <u>i</u> to install spring in coach.
- 5-8. GENERAL INFORMATION
 - a. Leaf Spring Specifications.

SPRING ASSEMBLY

DATA

Length	. 5 feet 4 inch (approx)
Width	. 3 inches
Number of leaves	. 10
Bushings (Spring-eye)	. Elastomer cushion
	(bonded to bubular steel)
Capacity	. 10, 200 pounds

b. Lubrication of Leaf Spring. Lubricate leaf spring as follows:

- (1) Loosen the four nuts on the U-bolts attaching the spring (center) support plate.
- (2) Remove the nuts, bolts, and spacer tubes attaching the clips (clamps) located near outer ends of spring.
- (3) Jack up front end of coach at the two forward jack points (see figure 5-2) until both front wheels are off the ground.
- (4) Clean any dirt or road grime from spring with stiff bristle (or wire) brush or other suitable method.
- (5) Using a suitable prying device, separate spring leaves (one at a time) as far as possible and coat areas between leaves with Valvoline "TECTYL 400-C".

NOTE

Do not lubricate shackle pin bushings in the lower spring eyes.

- (6) Lower coach and remove jacks.
- (7) Install bolts, spacer tubes and new $3/8 \times 16$ nuts in the two spring clips; peen bolt end to secure nut in place.
- (8) Torque four U-bolt muts to 171 to 189 foot pounds.



URGENT
MANDATORY

	ROUTINE
X	INFORMATIONAL

DATE March 14, 1973 Service Bulletin NUMBER

UMBER 2905 40001

ATTENTION: SERVICE MANAGER	GROUP 5
This Service Bulletin contains procedures for correction	Front Suspension
of a noise nuisance which could occur in the leaf spring	SUBJECT
of the front suspension system. The spring leaves are initially coated with Valvoline "TECTYL 400-C" lubricant,	Leaf Spring
rust inhibitor, however, after operation in certain wet	
or hot weather some of the lubricant may dissipate, re-	
sulting in squeaking. When this condition is encounter-	
ed, relubricate spring as follows:	MODEL (S)
1. Loosen the four nuts on the U-bolts attaching the	AFFECTED
spring (center) support plate.	2900R
2. Remove the nuts, bolts and spacer tubes attaching	
the clips (clamps) located near outer ends of spring.	
3. Jack-up front end of coach at the two forward jack	
points (see figure 4-18 on page 4-23 of the owners	•
manual) until both front wheels are off the ground.	(Factory Use Only)
4. Clean any dirt or road grime from spring with stiff	added to:
bristle (or wire) brush or other suitable method.	
5. Using a suitable prying device, separate spring	OWNER MANUAL(S)
leaves (one at a time) as far as possible and coat areas	
between leaves with Valvoline "TECTYL 400-C".	SERVICE MANUAL (S)
NOTE: Do not lubricate shackle pin bushings in the	
lower spring eyes.	PARTS MANUAL (S)
6. Lower coach and remove jacks.	•
7. Install bolts, spacer tubes and new 3/8 x 16 nuts in	WARRANTY MANUAL (S)
the two spring clips; peen bolt end to secure nut in	
plate.	OTHER
8. Tighten the 4 U-bolt nuts to a torque of 171 to 189	
foot pounds.	
NOTE: Periodically check U-bolt tightness at intervals	
specified in the owners manual.	
·	

URGENT		ROUTINE
MANDATORY	Y	INFORMATIONAL

Service Bulletin

DATE 18 September 1973 NUMBER 2905 40003

GROUP ATTENTION: SERVICE MANAGER NOTE FRONT SUSPENSION SUBJECT This Service Bulletin cancels and replaces Service Bulletin Number 2905 40002, dated 22 August 1973, of same title. Remove can-INSTALLATION OF celled bulletin from files and destroy. SPACERS FOR Binding between shackle and leaf of spring has occurred SPRING SHACKLE on some coaches. If condition exists it should be corrected by installing spacers. Inspect as shown in figure 1, then accomplish the following procedures, if MODEL (S) required, at points where binding is evident. AFFECTED Refer to Service Manual Group 5, Front Suspension, and jack coach in accordance with paragraph 5-3b, steps (1), (2), and (4). 2900R Place small jack under spring-eye (center area between shackle halves) and raise enough to relieve (neutralize) tension. 3. Remove cotter pins from ends of each shackle pin (Factory Use Only) nut. Information 4. Remove nuts and washers from end of each shackle added to: pin, retain washers. 5. Remove shackle and retain; do not remove shackle OWNER MANUAL (S) pins. NOTE SERVICE MANUAL (S) It may be necessary to further adjust jack, installed in step 2, to free PARTS MANUAL (S) shackle from pin 6. Install new spacer(s) (5101135-100) on shackle pin WARRANTY MANUAL (S) ends, as required, to obtain 1/16 inch clearance. 7. Reinstall shackle on pins (check for specified clearance), then secure with washers retained from OTHER step 4 and new nuts provided; tighten nuts 110 to 120 foot pounds; insert cotter pins. Inspect, and if necessary, repeat steps 2 through 8 on opposite side of coach where binding is evident. Remove jack and jack stands, then remove wheel chocks from rear wheels. John L. Strever Service Manager

☐ URGENT

☐ ROUTINE


☐ MANDATORY

☐ INFORMATIONAL

Service Bulletin

DATE 18 September

2905 40003



☐ URGENT

ROUTINE

☐ MANDATORY

☑ INFORMATIONAL

Service Bulletin
NUMBER 2905-40004

ATTENTION: SERVICE MANAGER	GROUP -
DESCRIPTION	5 .
This service bulletin is issued to help dealers overcome the noise problem that is due to the transverse front spring assembly. On early Production coaches a ten-leaf spring was used on the front suspension. If coach owner is experiencing a noisy front end and the distance between the upper suspension arm and rubber bump stop is h' or more, add liner kit to the ten-leaf spring. If distance from upper suspension arm to rubber bumper stop	FRONT =
is less than h" an 11-leaf spring (5106719) should be substituted for the ten-leaf. The new 11 leaf spring assembly (5106719) has spring liners built in at the factory and need not be disassembled. KIT CONTENTS (5101800-R004)	MODEL (S) AFFECTED 2900R MOTOR HOME SERIAL 00001
MCD NUMBER DESCRIPTION QTY	to 00588 APPROX
5106738 Laminate, leaf (3" wide, cut to length-10 pcs) 1	(Factory Use Cnly)
5106734 Bolt, Spring Center 1	Information added to:
5101821 U-Bolt, Spring Mounting 2	
INSTRUCTIONS	OWNER MANUAL (S)
 Remove spring assembly from coach per Group 5 of Service Manual. 	SERVICE MANUAL (S)
 Disassemble spring by removing nut from spring center bolt and lifting off individual spring leaves. 	PARTS MANUAL (S)
 Thoroughly clean spring leaves and coat each leaf with a good grade of heavy-duty multi-purpose automa- tive grease. 	WARRANTY MANUAL (S
NOTE	ОТНЕЯ
If spring leaves are equipped with nylon tips, leave tips in place and cut off end of laminating strip.	
4. Place liners on spring leaves so that liner matches leaf and reassemble spring.	



FMC Corporation
Motor Coach Division
CDB Brokaw Road Box 664 Santa Clara California 95052

☐ URGENT

☑ INFORMATIONAL

Service Bulletin

DATE October 15, 1974 NUMB	ER 2905-40004
ATTENTION: SERVICE MANAGER	<u> </u>
5. Use new center bolt (5106734) in reassembled spring. Use existing center bolt nut during reassembled	
6. Install spring assembly in position on coach use new U-Bolts (5101821) to hold spring to coach fi	TEME. SPRING
7. Load coach to its normal operating weight as realign wheels in accordance with Service Bulletin 2907-40002.	
WARRANTY REIMBURSEMENT	MODEL (S) AFFECTED
We will allow a maximum of 3 labor hours and reimber ment for parts on a properly filled out warranty of (form RVD69) for this modification. Authorization dealer to proceed must be obtained from Motor Coacivision Service Department prior to performing the	laim 2900R for MOTOR HOME h Di- SERIAL 00001
	(Factory Use Only)
Max Snavely Service Manager	OWNER MANUAL(S)
	SERVICE MANUAL (S)
	PARTS MANUAL (S)
	WARRANTY MANUAL (S)
	OTHER
•	•

ATTENTION: SERVICE MANAGER

☐ ROUTINE

5 & 6

HEAVY

SHOCK

ABSORBER

DUTY

SUBJECT

MODEL (S)

AFFECTED .

ALL TRANSIT COACHES

Service Bulletin

NUMBER 2905-40005 DATE GROUP

INSTALLATION CONFIGURATION HEAVY DUTY SHOCK ABSORBERS M17029 TRANSIT COACHES M17030 5109260 5109259 M18210 5109258 M18166 5109260 M17030 M17075. REAR SUSPENSION KIT Parts Required for Installation (Per Shock)

1 - M17029

Nut (top)

1 - M17075

Nut (bottom)

1 - M18210

Bolt (top)

1 - M18166

Bolt (bottom)

7 - M17030

Washer

4 - 5109259

Washer

2 - 5109260

Bushing

1 - 5109258

Shock


DATE.

■ MANDATORY

☑ INFORMATIONAL

Privice Bulletin November 15, 1976

2905-40005



FRONT SUSPENSION KIT

Parts Required for Installation (Per Shock)

2 - M17029 Nut

4 - M17030Washer

Bolt (top) 1 - M18210

1 - M18074Bolt (bottom)

2 - 5109259Washer

2 - 5109260 Bushing

1 - 5109258 Shock



FMC Corporation
Motor Coach Division
333 Brokaw Road Box 664 Santa Clara California 95052

	URGE	NI
--	------	----

ROUTINE

■ MANDATORY

☑ INFORMATIONAL

Service Bulletin

2905-40005 **GROUP** ATTENTION: SERVICE MANAGER 5 & 6 SUBJECT On page T6-3 delete existing items 24 through 27 and substitute the following: HEAVY DUTY Item 24 5109258 SHOCK ABSORBER . SHOCK Item 25 M18210 BOLT, Upper ABSORBER Item 26 M17029 NUT, Bolt Item 27 M17030 WASHER, Bolt BOLT, Lower M18166 5109259 WASHER, Cupped 5109260 BUSHING, Bolt Remove and install shock absorbers in accordance with instructions contained in Transit Series Service Manual Groups 5 & 6. Substi-MODEL (S) tute new heavy duty shock absorber parts for existing shock **AFFECTED** absorbers. ALL TRANSIT COACHES

☐ ROUTINE

☐ MANDATORY

☑ INFORMATIONAL

November 15, 1976 Pervice Bulletin

/	V	V	2	V			
	N	٧L	J٨	ИB	Ε	R	_

2905-40005

DATE November	13, 13,0		MOMOCH		
				GROUP	
ATTENTION: SEF	RVICE MANA	GER		5 & 6	
			,	1	
DESCRIPTION			•	SUBJECT	
		the beauteduty s	hock absorbers		
This bulletin pr	ovides data	on the heavy-duty s	ately the existing	HEAVY	
required for tra	insit coache	rear) are superseded	by shock absorber	DUTY	
shock absorbers	(front and	rear) are supersucc		SHOCK	
#5109258.				ABSORBER	
	:100258) tril	1 fit both front and	rear applications		
The new snock (l etock unde	r MCD numbers 510099	10 and 5100991 which		
and replaces al.	milable for	transit application	1.		
Your initial or	der for the	new shocks will requ	ire all the parts		
shown on pages	3. and 4	of this bulletin.			
REPAIR PARTS CA	TALOG CORREC	TIONS		MODEL (S)	
		= :+=== ED through i	52 and substitute	AFFECTED	
On page T5-4 de	lete existi	ng items 60 through	JE dia sansare	,	
the following:	*			ALL TRANSIT	
E A	5109258	SHOCK ABSORBER :	2	COACHES	
Item 60	M18074	BOLT, Lower	2	COACILIS	
Item 61	M18074 M18210	BOLT, Upper	2		
Item 62	M17029	NUT, Bolt	4		
Trem oz	M17030	WASHER, Bolt .	4		
1	5109260	BUSHING, Bolt	4		
	5109259	WASHER, Cupped	4		
~ ~ •	7.4	ng items 58 through	62 and substitute		
On page T5-8 de the following:	elece exizer	119 1 CC1112 20 411-1-211			
the lottowing.			_		
Item 58	5109258	SHOCK ABSORBER	2		
Item 59	M18210	BOLT, Upper	2		
Item 60	M17029	NUT, Bolt	4		
Item 61		WASHER, Bolt	2		
Item 62	M18074	BOLT, Lower	2		
	5109260	BUSHING, Bolt	4 4		
	5109259	WASHER, Cupped	4		
F.F.	.			ļ	
1			• . <u>T</u> i		
Han.					
AS U					
710 0	▼ 8 → 6 b + 1 m m = 1	and the second s	₹	1	

FMC Corporation

Migror Coach Division 300 Brokew Road | Edx 634 Santa Clara California 95052 (408) 2340111

7-26-76

FMC

Dear FMC 2900R Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Act.

FMC/MCD has determined through reports and inspections that a safety related defect exist in the <u>front suspension system</u> of Vehicle 1 through 645.

The parts involved are the upper "A" arm shaft and cam bushings. The failure of the self-lubricating bushing is caused by a misaligned condition of the upper "A" arm cam adjustment. The unequal adjustment of the upper "A" arm forward and aft cams causes a torsional stress on the "A" arm shaft. This, in turn causes premature wear of the bushing surface permitting contact of the steel "A" arm shaft and steel backing sleeve of the bushing. Penetration of moisture or salt-laden road water to the steel surfaces can over a period of time cause shaft salzure.

FMC will correct this problem by furnishing an oil impregnated bushing design with a better lubricating capacity and correct all vehicles with unequal adjustments of upper "A" arm cam adjusters. The parts for the recall are available as of August 1, 1976. Parts will be shipped directly to FMC coach owners via United Parcel Service. Upon delivery of the parts package, you or someone within your household will be required to sign for it.

Enclosed in the parts package you will find Service Bulletin \$2905-10001 giving detailed instructions on pages 1 through 9 on how to remove old parts and install new ones. Pages 13 through 15 gives a list of former FMC Dealers and authorized FMC Service Centers. This list will allow you to confirm appointments before taking your coach in for regair.

For those coaches found to have an unequal upper "A" arm cam adjustment, please refer to Page 11, Para. (f) for correct setting. The yellow self-addressed Status Report Card (MCD Form 79) included in parts package is to be completed by Service Center and dropped into the nearest mailbox. The white self-addressed card enclosed with this letter is to be completed if you no longer own the FMC 2900R vehicle or can furnish information regarding the new owner. It is imperative that you comply with this recall campaign, it is conceivable that an accident could occur. The upper "A" arm shaft due to torsional stress and seizure could snap at both ends, thus allowing wheel and spindle assembly to tilt outward resulting in loss of control of vehicle.

FMC/MCD no longer has a Dealer organization and upon contact some Dealers may refuse to do the work or require you to pay for labor, or you may feel the former Dealer or FMC Authorized Service Center is not within a reasonable distance. If service is refused, you may contact a local front-end shop to do the work. This arrangement should be coordinated with Customer Service before beginning the work. Customer Service can be reached by calling (408) 289-3665.

If you are requested to pay for service rendered by former FMC Dealers or Service Centers, please forward paid invoice to FMC/MCD Warranty Dept., 333 Brokaw Road, Box 664, Santa Clara, CA. 95052, you will be reimbursed promptly.

We wish to advise you, the coach owner, involved in this recall that if work has not been performed at NO CHARGE or you have not been reimbursed, you may contact the Administrator of National Highway Traffic Safety Administration, Washington, D.C. 20590.

Sincerely,

אמקבארם כ עקקבה

Customer Service Manager

HRR/pf



FMC Corporation Motor Coach-Division 333 Brokaw Road Box 664 Santa Clara California 95052

X URGENT	
----------	--

ROUTINE

	MA	ND	AΤ	O	R١
--	----	----	----	---	----

☐ INFORMATIONAL

DATE July 26, 1976 Pervice Bulletin NUMBER.

2905-10001

ATTENTION: SERVICE MANAGERS AND OWNERS	GROUP
THE PARTY OF THE P	5
DESCRIPTION	SUBJECT
This bulletin provides instructions for replacement of the front upper suspension arm alignment cam bushings and washers with lubricated bushings and washers. Replacement is necessary due to the poor lubricating qualities of the original bushings, which may cause seizing of the alignment cam and mount block and subsequent damage or failure of the upper suspension arm.	Upper Suspensior
COMPLIANCE	
Service Managers and owners must comply with this bulletin as soon as possible per recall notification #A0507.	MODEL (S) AFFECTED
MANPOWER	
Estimated accomplishment time for one mechanic is 4.0 hours. FMC/MCD will reimburse for labor up to a maximum of 4.0 hours.	Coaches 00001 to 00645.
MATERIAL	
Replacement parts supplied at no charge by FMC/MCD are:	
4 ea. #M17031 Steel Washers (Small) 4 ea. #M17198 Steel Thrust Washers (Large) 4 ea. #5109266 Oil Impregnated Washers (Large) 4 ea. #5109271 Oil Impregnated Washers (Small) 4 ea. #5109265 Bushings 4 ea. #5109268 Felt Packings 4 ea. #5109267 Oilers 6 ea. #M25055 Cotter Pins 8 ea. #M17002 Locknuts	
See Last page for current list of repair centers.	

MCD-84 (2-75)



FMC Corporation Motor Coach Division 333 Brokaw Road Box 664 Santa Clara California 95052 ☑ URGENT

ROUTINE

☐ MANDATORY

☐ INFORMATIONAL

DATE July 26, 1976 Pervice Bulletin NUMBER_

NUMBER 2905-10001

		GROUP
ATT	ENTION: SERVICE MANAGERS AND OWNERS	
		5
ACC	OMPLISHMENT INSTRUCTIONS	SUBJECT
		3063501
1.	Set parking brake and place a chock behind each rear tire.	Upper Suspension
2.	Jack up front end and install a truck jack stand	
	under each front jacking point (figure 1).	Arm.
3.	Remove front wheels to gain access to the suspension arms.	
4.	Place a support under each front hub, and raise hub	
	enough to relieve pressure on shock absorber	
5.	(figure 2). Remove lower shock absorber locknut, bolt, and	
	washers.	
	NOTE	MODEL (S)
	It may be necessary to relieve pressure on	AFFECTED
	shock absorber by jacking up control arm.	
6.	Note position of cam notch in relation to cam lock, and scribe a mark from the cam to the alignment cam	Coaches 0001
	block (figure 3). (Identify blocks left, right,	to 00645.
,	front and rear.)	
7.	Loosen four bolts on top of each alignment cam block and remove block from arm spindle assembly (figure	
	3).	
8.	Remove four locknuts and bolts holding ball joint to	
9.	suspension arm. Discard locknuts. Remove upper suspension arm.	
10.	Place suspension arm in vise; remove cotter pin and	
	nut, then remove cam and two washers from spindle (figure 4). Retain thin teflon coated washer (with	
	small hole), and nut. Discard cotter pin.	
	NOTE	!
	If cam is frozen on spindle, heat cam with a torch, and use a hammer and block of wood	
	or other soft material to remove it from the	
	spindle.	
į	NOTE	
	When using vise, protect parts with a piece of	
11.	scrap aluminum or other soft material. Using a 13/16 Proto spark plug socket (no. 5326),	
	and a 1-1/8 deep socket or a piece of pipe; place	•
	cam in vise, and press out the old bushing (figure 5	P
1		
1		
1		Į



☑ URGENT

□ ROUTINE

☐ MANDATORY


☐ INFORMATIONAL

Service Bulletin

DATE July 26, 1976

NUMBER_

2905-10001






Figure 2. Hub Support.

MCD-84 (2-75)

Page 3 of 15



FMC Corporation
Motor Coach Division
333 Brokaw Road Box 664 Santa Clara California 95052

☑ URGENT

■ MANDATORY

☐ ROUTINE

☐ INFORMATIONAL

Service Bulletin

DATE July 26, 1976

2905-10001

GROUP




Figure 3. Cam to Block Scribe Mark.




Figure 4. Removing Cam.

5 SUBJECT

Upper Suspension Arm.

MODEL (S) **AFFECTED**

Motor Coaches 00001 to 00645.

MCD-84 (2-75)

Page 4 of 15

2905-10001

☐ MANDATORY

☐ INFORMATIONAL

DATE July 26, 1976 Service Bulletin NUMBER.

ATTENTION: SERVICE MANAGERS AND OWNERS	GROUP
	5
	SUBJECT
12. Clean spindle and cam in dry cleaning solvent, then remove rust or burrs with crocus cloth and	Upper Suspension
wire brush. Be sure you clean all surfaces of the cam, especially the bushing bore. Wash it off	Arm
again in solvent. 13. Inspect spindle-to-suspension arm weld for cracks.	
If you find a crack, do not attempt to reweld it. Order a replacement arm and spindle assembly	
#5100066-W01 from FMC/MCD. 14. Place cam in vice with outboard (hex) end up.	
Punch mark at dead center of hex. Using a 3/16 drill bit, drill a hole approximately 1-1/4 to	
<pre>l-1/2 inch deep. Then drill a hole through the side of the cam (same size), to intersect the first</pre>	MODEL (S) AFFECTED
hole and into the bushing bore (figure 6). 15. Counterbore hole in outboard (hex) end of cam using	
a 3/8 drill bit. The counterbore should be at least 3/8 inch deep. Clean out both holes.	
16. Position oiler to cam, place cam in vise, and pressoiler into counterbored hole.	to 00645.
17. Chamfer inboard end of cam bore. Slide new oil impregnated washer (large), over new bushing, and	
position cam and bushing in vise. Take care to protect oiler. Press bushing into cam (figure 7).	
End of bushing must be flush with face of oil impregnated washer (figure 8).	
18. Place suspension arm in vise. Soak new felt pack- ing in 140 weight gear oil. Assemble cam on spindle as follows (figure 9):	· · · · · · · · · · · · · · · · · · ·
a. New Steel thrust washer (large).b. Retained teflon coated bushing washer	
<pre>(with small hole). c. New oil impregnated washer (large).</pre>	
d. Cam with new bushing and oiler.e. New oil-soaked felt packing.	
f. New oil impregnated washer (small). g. New steel washer (small).	
h. Retained slotted nut (finger tight).	



FMC Corporation
Motor Coach Division
333 Brokaw Road Box 664 Santa Clara California 95052

☑ URGEN	T
---------	---

□ MANDATORY

ROUTINE

☐ INFORMATIONAL

Service Bulletin

DATE July 26, 1976

2905-10001




Figure 5. Removing Old Bushing.




Figure 6. Drilling Com.

GROUP

5

SUBJECT

Upper Suspension Arm.

MODEL (S) AFFECTED

Motor Coaches 00001 to 00645.

MCD-84 (2-75)

Page 6 of 15



FMC Corporation
Motor Coach Division
333 Brokaw Road Box 664 Santa Clara California 95052

\mathbf{x}	UR	GE	NT
	O11	\neg	141

ROUTINE

	NΑΛ	NIO.	۸٦	\sim	o	v
LJ '	IVIA	שעו	м	···	n	Ţ

☐ INFORMATIONAL

Service Bulletin NUMBER.

DATE July 26, 1976

ATTENTION: SERVICE MANAGER

2905-10001




Figure 7. Pressing New Bushing into Cam.




Figure 8. End of Bushing Flush with Washer.

GROUP

SUBJECT

Upper Suspension

MODEL (S) **AFFECTED**

Motor Coaches 00001 to 00645.

MCD-84 (2-75)

Page 7 of 15



DATE July 26, 1976

0

x	UR	GE	NT
نت	\sim 11	\sim $-$	

ROUTINE

2905-10001

	MANDATO	RY
_	1411 (11 12 11 11 1	

☐ INFORMATIONAL

Service Bulletin

GROUP ATTENTION: SERVICE MANAGER **RETAIN** SUBJECT EFLON COATED NEW STEEL THRUST WASHER OIL IMPREGNATED WASHER (LARGE) Upper Suspension WASHER (LARGE) Arm. NEW STEEL WASHER (SMALL) NEW OIL IMPREGNATED WASHER (SMALL) MODEL (S) RETAINED **AFFECTED** SLOTTED NUT **FELT** Motor Coaches **PACKING** 00001 to 00645.

Figure 9. Assembling Cam.



ட	UKGENI	

■ MANDATORY

INF	ORN	TAN	IONAL

DATE July 26, 1976 Pervice Bulletin NUMBER 2905-10001

ATTENTION: SERVICE MANAGERS AND OWNERS	GROUP
ATTENTION. SERVICE MANAGERS AND OWNERS	5
19. Lubricate cam through oiler with 140 weight gear oil. Hold finger over bleeder hole until air is bled out and oil appears. Tighten slotted cam nut finger tight and turn to next slot on nut, secure with new cotter pin.	SUBJECT Upper Suspension Arm.
20. After all cams have been reworked, install upper suspension arm and spindle assembly in lower half of alignment cam blocks.	
21. Install top half of each alignment cam block (identified to bottom half). Align scribe marks and secure with four bolts and lockwashers. Tighten bolts to 32 to 34 foot pounds torque. Check suspension arm for binding.	,
22. Position ball joint to spindle assembly, and secure with four bolts and new locknuts. Tighten locknuts to 36 to 38 foot pounds torque.	MODEL (S) AFFECTED
23. Position shock absorber, and secure with washers, bolt and locknut. Tighten locknut to 212 to 234 foot pounds torque.	Coaches 00001
24. Remove hub supports; install wheels, and remove jack stands.	to 00645.
25. Lower front end of vehicle and remove rear tire chocks.	

Group 7 Model 2900R

f. Wheel Alignment. Proper wheel alignment ensures that the suspension and steering systems will function to provide optimum handling, steering, and stability with minimum tire wear.

Six adjustments are required to properly align the coach suspension and steering system.

Levelling — Coach should be level laterally (side-to-side) and the rear end should be 1/8 inch lower than the front.

Camber — The angle the top of the front wheel tilts out (positive) or (negative) in relation to true vertical. The coach front wheels tilt inward at the top at an angle of 1/2 degree negative camber.

Caster — The forward or rearward angle of tilt from true vertical of the steering spindle as established at lower and upper attachment points to the suspension arms. The spindle attachment point to the upper arm on the coach is aft of the lower attachment point. A centerline drawn from the spindle lower-to-upper attach points would, if viewed from the side, indicate the difference from true vertical to be 2 degrees positive caster.

Toe-out (front) — The difference in measured inches between the front edges (of outer tread edge) of the two front tires vs the difference of the rear edges when measured at approximately hub level. The coach measurement should indicate the front edge tire-to-tire distance to be 3/8 inch more than rear.

Toe-in (rear outboard wheels) — Measure same as front; should be 1/8 (plug 0, minus 1/16).

Steering wheel spoke positioning — see figure 7-1. Position spokes as shown, in accordance with paragraph 7-6f(6).

- (1) Levelling the Coach. Prior to wheel alignment, check levelling and adjust as required. The rear end of the coach should be 1/8 inch lower than the front. This can be adjusted as follows:
- (a) Place turntables (swivel pads) with lock-pins installed on a level, preferably concrete floor, directly in front of coach front and rear outboard wheels.

- (b) Drive coach straight onto turntables and center the tires on swivel pads; front wheels positioned straight ahead.
 - (c) Set parking brake.
- (d) Check all tires for 75 pounds pressure. Inflate or deflate, as required, to obtain specified psi.

Caution

A normal road-operating load should be on the coach for these procedures. Domestic and automotive systems serviced, holding tanks empty or low, normal kitchenware, supplies, and baggage in place in cabinets and closets.

- (e) Measure coach height at two front and two rear jack points, jot down location and measurements, and compare the figures. Each rear measurement should be equal and each should be 1/8 inch lower than the front end measurement. If these measurements are obtained, proceed to paragraph 7-6f(2); if not, perform steps (f) and (g) below.
- (f) Adjust rear end height by removing four cap screws and torsion bar anchor cover plate located on forward wall of each wheel well. To get access to the plate, pull the rubber strip inboard out of the retainer groove. Turn torsion bar anchor adjustment bolt, as required, to increase or decrease until specified rear end height is obtained.

NOTE

When adjusting, check left-hand and right-hand side measurements frequently, as adjustment on one side affects height of opposite side. Coach must be level laterally while maintaining proper height.

- (g) Reinstall access plates, and insert rubber strips upon completion of previous step.
- (2) Camber adjustment (fig. 7-1, 7-4, and 7-5). With coach leveled as specified in previous paragraph, adjust camber to (negative) 1/2 degree as follows:




Figure 7-5. Front Wheel Alignment

- (a) Loosen the nuts and bolts securing rod end clamps (fig. 7-1, item 6) to control link rod (fig. 7-1, item 14) on both right-hand and left-hand rods, at each end of each rod. Rods must be free to turn on threaded ends of sockets. Also loosen radius rod end clamps in same manner to accomplish later steps.
- (b) Using a John Bean "Dial-A-Matic" caster, camber and dual-level indicating device (fig. 7-5), or equivalent, magnetically attach to left-hand front wheel hub cap, with adapter, to get readings directly in line from spindle axle.
- (c) Remove the lock-pins from front wheel turntable swivel pads. Set to zero "0" reading on gage.
- (d) Remove the two hold-down bolts securing the alignment cam lock to each end of the forward and aft split-block mounts; remove locks (fig. 7-1, item 19).

Warning

To permit rotation of alignment cam, slightly loosen the two hold-down bolts remaining in the two split-block mounts. If loosened too far, they might strip-out, allowing wheel assembly to abruptly sag outward.

- (e) Check the camber for a 0 + 1/2 reading on the Dial-A-Matic by first rotating to center the cross-level bubble. Then turn the dial wheel to center the dial-level bubble. Read camber from the camber dial (large outer dial).
- (f) Adjust the forward and aft eccentric alignment cams equally, using a 1 and 7/8 inch socket, until a 1/2 degree negative camber reading is obtained. Tighten mount block bolts, then reinstall cam locks and secure with bolts; torque all bolts 32 to 34 foot-pounds.

- (g) Repeat procedures on right-hand wheel.
- (3) Caster Adjustment (fig. 7-5). With levelling and camber adjusted as outlined in preceeding steps, proceed to adjust caster to 2 degrees positive as follows:
- (a) Reinstall Dial-A-Matic as previously described, on left-hand hub cap.
- (b) Turn wheel to a 15-degree angle outboard (left-hand turn) setting on turntable gage. Center the cross and dial level bubbles on the Dial-A-Matic. Set caster dial to "0" by holding the dial wheel stationary and turning the hex knob to align the "0" line on the caster dial with the index mark on the parapet.
- (c) Turn until front of wheel is at a 15-degree angle inboard (right-hand turn) indication in turntable gage.
- (d) Center the Dial-A-Matic cross and dial level bubbles.
- (e) The Dial-A-Matic caster reading should be 2 degrees positive. If necessary, adjust by turning radius rod (use a pipe wrench if necessary).
- (f) Recycle wheel to all of the previous positions and verify that adjustment stays within allowable tolerance.
- (g) Repeat procedure on right-hand wheel.
- (h) Remove Dial-A-Matic and adapter from hub cap mount holes; reinstall hub cap attaching bolts (both sides).
- (4) Toe-out Adjustment (Front) (fig. 7-5). With levelling, camber and caster adjusted as outlined in preceeding steps, adjust toe-out 3/8 inches as follows:
- (a) Position front wheel straight ahead on turntable.
- (b) Use a 6-inch square and check that the lower aft-extending arm (fig. 7-1) on the bell-crank (left-hand side) is parallel with adjacent coach frame. If not parallel, loosen nuts and bolts on the clamps at each end of the drag link rod, which attaches the upper bellcrank arm to the pitman arm, and adjust lower arms until parallel; retighten clamps.
- (c) Make a preliminary toe-out check by measuring the distance between the frame and inboard edge of the wheel rim at the rear end of wheel; then measure at front end. The measurement at the front should be 3/16 inch more than the rear measurement.

- (d) Adjust, if required to obtain the toeout specified in previous step, by turning the control link rod which connects bellcrank to the spindle control arm.
- (e) Repeat steps (a), (c), and (d) on right-hand wheel.
- (f) Using a steel tape or other measuring device, measure the distance between the aft end of the right-hand and left-hand front wheel tires (at the outer thread edge approximately hub level); then measure at the front ends of the wheels. The distance at the front should be 3/8 inch more at the front than at the rear.
- (g) If toe-out specified in the previous step is not obtained, repeat step (d) on both right-hand and left-hand wheels until required toe-out is obtained.

NOTE

Retighten all linkage rod end clamps by tightening the attaching nuts and bolts at each end.

- (5) Toe-in Adjustment (Rear) (fig. 7-) Wile front toe-out adjusted as outlined about, check the rear outboard wheel toe-in and adjust, if required, as follows:
- Using a cord (twine or song) of approximally 30-foot length, wraptine end around right and outboard rear tirgle approximately hub lend. Secure to the integral side of tire. Pull cord to tand extend lend not coach to front tire, and source opposite and of cord to front tire same position as refer front wheels are positioned as a tasted previous procedures.
- (b) Check that and touches front tire fore and aft outboard taces evenly; then check for same condition a man outboard tire.
- (c) If rear or coard the surfaces do not contact cord both five and aft a par edges, adjust rear toe-in in accordance with the following steps (d) through (j). If cord is propely contacting tire surface, no further rear to the adjustments are no essary. Check opposite the
- (d) V fermine amount of rear where oe-in adjustmen (needed; if small, adjust only) the outboar trailing arm pivot mount block.
- (e) Loosen the four bolts securing the upper half of the split pivot block to the frame.

FORMER DEALERS AND AUTHORIZED

FMC SERVICE CENTERS

GENERAL GMC 2420 W. Bethany Home Road Phoenix, AZ 85015 (606) 242-4343 JIMMY'S RV CENTER, INC. 4610 E. Broadway Tucson, AZ 85711 (602) 795-4322

ARNOLD WIEBE PONTIAC-GMC P.O. Box 790 Corner Main & Bridge St. Visalia, CA. 93277 (209) 732-8814

HAL WATKINS RV COUNTRY 311 Daily Drive Camarillo, CA. 93010 (805) 484-2756

HAROLD ONKEN SALES 1938 W. 5th. San Bernardino, CA. 92411 (714) 885-4327

HAROLD ONKEN SERVICE 13990 Valley Blvd. Fontana, CA. 92410 (714) 882-2236

KENDON MOTOR HOMES 1358 Pacific Coast Highway Harbor City, CA. 90710 (213) 530-1331

CLIFFORD T. NUTT, INC. 2200 W. Coast Highway Newport Beach, CA. 92660 (714) 548-3339

FARLAND MOTORS 7895 East Prentiss Ave. Bldg. #43, Suite 100 Englewood, Colo. 80110 (303) 773-0323

CONNECTICUT CAMPER CENTER 260 W. River St. Box 249 Milford, CT 06460

WILSON COACHES, INC. 2533 S. State Extended P.O. Box 357 Dover, Del. 19901 (302) 697-7940

AMERICAN LAND CRUISERS 6356 Manor Lane S. Miami, FL 33143 (305) 665-3656

GLOBE MOTOR HOMES 4601 Gandy Blvd. Tampa, FL 33611 (813) 839-2654

HEINTZELMAN'S 808 N. Orange Ave. Orlando, FL 32802 (305) 422-4448

BILL SPREEN TRAVEL HOUSE ACKERMAN BUICK, INC. 4873 Buford Highway Chamblee, GA 30341 (404) 458-8907

ROBERTS AUTO, INC. 323 Caldwell Blvd. Nampa, ID 83651 (208) 466-9226

MOTOR VACATIONS Rt. 1 Box 128 Elgin, Ill 60120 (312) 695-9413

HEFNER CHEVROLET 500 E. State Blvd. Ft. Wayne, IND 46805 (219) 484-5566

DAVIS-MOORE 6215 E. Kellogg Wichita, KS 67218 (316) 685-0211

Sixth & Cherokee COLLARD CHEVROLET Leavenworth, Kansas 66048

COLEMAN OLDSMOBILE 7070 Florida Blvd. Baton Rouge, LA 70821 (504) 927-1240

STEUART FORD 9020 Lanham-Severn Road Lanham, MD 20801 (301) 459-1100

Page 13 of 15

BOB MOORE, INC. 875 Centre St. Brockton, MA 02402 (617) 583-1440

PAULSON MOTORHOMES 870 W. Columbia Ave Battle Creek, MI (616) 962-8737

ROSEMOUNT DODGE 14755 S. Robert Tr Rosemount, MN 55068 (612) 423-2241

2900 Pershall St. Louis, MO 63136 (314) 524-2900

WINKEL PONTIAC 900 Kietzke Lane Reno, NV 89505 (702) 329-0831

KEVAH KONNER, INC. Rt. #46 Pinebrook, NJ 07058 (201) 227-3100

HESS MOTOR COACH 13100 Central Ave. Albuquerque, NM (505) 296-0732

BALLANTYNE MH CENTEF 7447 Rte. 96 Victor, NY 14564 (716) 924-3264

HOLIDAY ON WHEELS 250 Kisco Ave. Mt. Kisco, NY 10549 (914) 241-1224

MITCHELL'S MOTORS 4319 High Point Rd. Greensboro, NC (919) 292-2187

SANDS MOBILE SALES, INC. 5267 N. Ridge Rd., Crt. 207 Madison, OH 44507 (216) 428-5131

VACATION VEHICLE CENTER 4736 Southeast 82nd. Portland, OR 97266 (503) 777-3846

BEN'S MOTORHOMES, INC. 1590 Whiteford Rd. York, Pa. 17402 (717) 755-9669

QUALITY COACH, INC. Rt. 309 Montgomeryville, Pa. 18936 (215) 643-2211

TOM HUTTON CO. 1710 E. Brooks Rd. Memphis, TN 38116 (901) 396-3960

MURPHY MOTOR MANORS Alcoa Highway/US 129 & 73 Alcoa, TN 37701 (615) 984-2380

FRIENDLY CHEVROLET CO. 3363 West Northwest Highway Dallas, TX 75209 (214) 526-8811

DALES MOBILE CHALET 2305 Gateway Blvd. S. El Paso, TX 79903 (915) 565-6901

FRANK GILLMAN MOTOR COACHES 7620 Bellaire Road Houston, TX 77036 (713) 771-3611

H. L. FRANKS, CO. 2050 S. Main St. Bountiful, UT 84010 (801) 292-7231 NORMANDIE MOTOR HOMES Alburg Trailer Park Alburg, VT 05540

NORTHWEST CORTEZ, INC. 16616 Pacific Coast Hwy. S. Seattle, WA 98188 (206) 244-1140

VAGABOND RV CENTER E. 7007 Sprague Ave. Spokane, WA 99206 (509) 928-9289

LIVABILITY, INC. 18230 W. Bluemound Rd. Brookfield, WI 53003 (414) 786-0650

PETER HUGHES MOTOR HOMES. RR 2 Orangeville Ontario, Canada (519) 941-0759

McLEMORE'S WHOLESALE & RETAIL 401 Mary Marr Winnsboro, Louisiana 71295 (318) 435-9081

MIDWAY RV REPAIR 8301 Bolsa Ave/Box 157 Midway City, CA. 92655 (714) 893-8102

FARLAND MOTORS
7895 East Prentiss Ave.
Bldg. #43, Suite #100
Englewood, Colo. 80110
(303) 773-0323

LIDDIE PONTIAC-GMC Highway 131 at I-65 Clarksville, Indiana 47130 (812) 282-7501

MAGIC CARPET REC VEH. 5124 Laurel Billings, MT 59101 (406) 252-6855

CONTINUED

COLUMBUS TRAILER SALES Rt. 2, Box 220A Columbus, NB 68601 (402) 564-7166

ENGSTROM MOTORHOME CENTER 17150 Boones Ferry Road Lake Oswego, Oregon 97034 (503) 635-3571

KELLERSTRASS BROS., INC. 2185 Wall Ave. P. O. Box 1067 Ogden, Utah 84402 (801) 393-0227

FMC Corporation

Motor Coach Division 333 Brokaw Road Box 664 Santa Clara California 95052 (408) 2890111

January 10, 1977



Dear FMC Motor Coach Owner:

In August of 1976, FMC Motor Coach Division started a recall campaign A0507 involving the first 645 motor coaches built. This campaign involved replacement of cam bushing on the left and right front upper "A" arm. In addition to this we added a kit and instruction to improve the lubrication in this area.

FMC wishes to thank those 308 FMC coach owners that have reported taking part in this campaign. FOR THOSE WHO HAVE NOT, WE WISH TO IMPRESS UPON YOU THE DANGER THAT EXISTS IF YOU DO NOT HAVE THE WORK DONE AS SOON AS POSSIBLE.

We wish to apologize for the delay of payment for those of you who have turned in your claims! Due to the continued cutback of the Motor Coach Division personnel, our Accounting Dept. is behind. Please be assured you will be paid for the time called out in the service bulletin #2905-10001.

FMC Motor Coach Division wishes you all a Happy and Prosperous New Year.

Sincerely,

HARRY'R. RICHARDS

Customer Service Manager

HRR/pf