



FMC Corporation
Recreational Vehicle Division
133 Brown Road Box 664 Santa Clara, California 95052

☐ URGENT

☐ ROUTINE

☐ MANDATORY

☒ INFORMATIONAL

Service Bulletin

DATE 10 August 1973

NUMBER 29004 0001

OWNERS, DEALER SALES, AND
ATTENTION: SERVICE MANAGERS

GROUP 0

✓ This service bulletin serves to correct certain coach specifications contained in Section 6 of the 2900R Owner's Manual. On page 6-1 under paragraph entitled DIMENSIONS change Width (overall) to read 8 feet 10 inches, Height (maximum) to read 9 feet 1 inch, and correct illustration accordingly.

SUBJECT

COACH
SPECIFICATIONS

✓ On page 6-2 under paragraph entitled BATTERIES change Domestic to read two each, under drivers floor board, change Make to Gould #PB220 6 volts RVD 5101798, change Ampere Hour to 220.

MODEL (S)
AFFECTED

2900R

✓ On page 6-2 under paragraph entitled ENGINE change Make and Model to read I440-3-4001 beginning with Coach Serial Number 00047 and up.

(Factory Use Only)
Information
added to:

✓ On page 6-3 under paragraph entitled ENGINE (continued) change Oil Filter Type to Full Flow, Chrysler 3549957, Carburetor to Chrysler 3698398, Alternator to Chrysler 3412354 85-amp, Spark Plugs to Champion 8L-9Y. All of the above changes effective with the 1440-3-4001 engine.

OWNER MANUAL (S)

SERVICE MANUAL (S)

PARTS MANUAL (S)

WARRANTY MANUAL (S)

OTHER

Does NOT APPLY TO COACH
5.
✓ On page 6-4 under paragraph entitled DIFFERENTIAL change to Rockwell Standard JF-140-X2 effective with Coach Serial Number 00257 and up.

✓ On page 6-5 under paragraph entitled ELECTRICAL - DOMESTIC (continued) delete Oven Light 50w - 12 v, change Range Light to read Range and Oven Light 15w - 12 v, change Circuit Breakers to Branch - Fusible Switches 4-20 amp, G-20.



FMC Corporation
Recreational Vehicle Division
233 Brockway Road Box 664 Santa Clara, California 95052

☐ URGENT

☐ ROUTINE

☐ MANDATORY

☒ INFORMATIONAL

Service Bulletin

DATE 10 August 1973

NUMBER 29004 0001

OWNERS, DEALER SALES, AND
ATTENTION: SERVICE MANAGERS

GROUP 0

Under paragraph entitled AIR CONDITIONING change automotive BTU Output Maximum (A/C unit) to 28,000 BTU Output-Maximum (heater/defroster) to 36,000, and Domestic BTU Output-Maximum (dual units) to 22,000.

SUBJECT

COACH
SPECIFICATIONS


Under paragraph entitled DOMESTIC EQUIPMENT add under Furnace the BTU input of 30,000 and the BTU output of 22,500.

MODEL (S)
AFFECTED

2900R

These pages will be corrected on the next change to the Owner's Manuals. Please file this bulletin in section 6 of your Owner's Manual until corrected pages have been issued.

Thank you,



John L. Strever
Service Manager

(Factory Use Only)
Information
added to:

OWNER MANUAL (S)

SERVICE MANUAL (S)

PARTS MANUAL (S)

WARRANTY MANUAL (S)

OTHER